

03500.013975.1



PATENT

Cole

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
	:	Examiner: Mark H. Paschall
NOBUMASA SUZUKI, et al.)	
	:	Group Art Unit: 3742
Appl. No.: 09/816,359)	
	:	
Filed: March 26, 2001)	
	:	
For: MICROWAVE APPLICATOR, PLASMA)	
PROCESSING APPARATUS HAVING	:	
SAME AND PLASMA PROCESSING)	
METHOD	:	
)	
U.S. Patent No.: 6,870,123	:	
)	
Issued: March 22, 2005	:	December 1, 2005

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate
DEC 07 2005
of Correction

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

12/05/2005 MM0HAMM1 00000014 6870123

01 FC:1811

100.00 OP

DEC 7 2005

Patentees' undersigned attorney may be reached in our Costa Mesa,
California office by telephone at (714) 540-8700. All correspondence should continue to
be directed to our address given below.

Respectfully submitted,



Frank L. Cline
Attorney for Patentees
Registration No.: 42,419

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

CA_MAIN 105710v1

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,870,123
DATED : March 22, 2005
INVENTOR(S) : NOBUMASA SUZUKI, et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

(63)

"Continuation-in-part of application No. 09/426,744," should read --Continuation-in-part of application No. 09/426,774,--.

COLUMN 1:

Line 6, "Ser. No. 09/426,744" should read --Ser. No. 09/426,774--.

COLUMN 5:

Line 21, " λ_s ." should read -- λ_s --.

Line 62, " l_g of" should read -- l_g of--.

COLUMN 10:

Line 16, "waveguide)" should read --waveguide)--.

COLUMN 12:

Line 54, "wherein n_1 ." should read --wherein n_1 --.

COLUMN 13:

Line 29, " $n_g (=l_g/\lambda_g)$ " should read $n_g (=l_g/\lambda_g)$ --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,870,123

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,870,123

DATED : March 22, 2005

INVENTOR(S) : NOBUMASA SUZUKI, et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14:

Line 62, "n¹ is 3," should read --n₁ is 3,--.

COLUMN 17:

Line 28, "ratio n^g" should read --ratio n_g--.

Line 29, "number n¹" should read --number n₁--.

COLUMN 18:

Line 14, "length 1_g" should read --length l_g--.

COLUMN 22:

Line 18, N₂," should read --NO₂,--.

Line 59, "TE₁₀. mode" should read --TE₁₀ mode--.

COLUMN 35:

Line 19, "wherein n," should read --wherein n₁--.

Line 36, "container," should read --container;--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,870,123

No. of add'l. copies
@ 30¢ per page

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,870,123
DATED : March 22, 2005
INVENTOR(S) : NOBUMASA SUZUKI, et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

(63)

"Continuation-in-part of application No. 09/426,744," should read --Continuation-in-part of application No. 09/426,774,--.

COLUMN 1:

Line 6, "Ser. No. 09/426,744" should read --Ser. No. 09/426,774--.

COLUMN 5:

Line 21, " λ_s ." should read -- λ_s --.

Line 62, " l_g of" should read -- l_g of--.

COLUMN 10:

Line 16, "waveguide)" should read --waveguide)--.

COLUMN 12:

Line 54, "wherein n_1 ." should read --wherein n_1 --.

COLUMN 13:

Line 29, " $n_g (=l_g/\lambda_g)$ " should read $n_g (=l_g/\lambda_g)$ --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,870,123

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,870,123

DATED : March 22, 2005

INVENTOR(S) : NOBUMASA SUZUKI, et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14:

Line 62, "n¹ is 3," should read --n₁ is 3,--.

COLUMN 17:

Line 28, "ratio n^g" should read --ratio n_g--.

Line 29, "number n¹" should read --number n₁--.

COLUMN 18:

Line 14, "length l_g" should read --length l_g--.

COLUMN 22:

Line 18, N₂," should read --NO₂,--.

Line 59, "TE₁₀ mode" should read --TE₁₀ mode--.

COLUMN 35:

Line 19, "wherein n," should read --wherein n₁--.

Line 36, "container," should read --container;--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,870,123

No. of add'l. copies
@ 30¢ per page

